AD			

#### **MEMORANDUM REPORT ARCCB-MR-97009**

# AMBIENT TEMPERATURE TESTING OF METALLIC MATERIALS EXPOSED TO PROPELLANT COMBUSTION ENVIRONMENTS CONTAINING HYDROGEN

G. N. VIGILANTE P. J. COTE J. H. UNDERWOOD

**MARCH 1997** 



# US ARMY ARMAMENT RESEARCH, DEVELOPMENT AND ENGINEERING CENTER CLOSE COMBAT ARMAMENTS CENTER BENÉT LABORATORIES WATERVLIET, N.Y. 12189-4050



APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

19970429 190

DTIC QUALITY INSPECTED 1

#### DISCLAIMER

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

The use of trade name(s) and/or manufacturer(s) does not constitute an official indorsement or approval.

#### DESTRUCTION NOTICE

For classified documents, follow the procedures in DoD 5200.22-M, Industrial Security Manual, Section II-19 or DoD 5200.1-R, Information Security Program Regulation, Chapter IX.

For unclassified, limited documents, destroy by any method that will prevent disclosure of contents or reconstruction of the document.

For unclassified, unlimited documents, destroy when the report is no longer needed. Do not return it to the originator.

# REPORT DOCUMENTATION PAGE

Form Approved

OME No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information, Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA. 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave blank	) 2. REPORT DATE	3. REPORT TYPE A	3. REPORT TYPE AND DATES COVERED		
•	March 1997	Final			
4. TITLE AND SUBTITLE AMBIENT TEMPERATURE TESTIN MATERIALS EXPOSED TO PROPE ENVIRONMENTS CONTAINING H	NG OF METALLIC			NG NUMBERS MS No. 6111.01.91A1.100	
6. AUTHOR(S)					
G.N. Vigilante, P.J. Cote, and J.H. Und	derwood				
7. PERFORMING ORGANIZATION NA	ME(S) AND ADDRESS(ES)			RMING ORGANIZATION T NUMBER	
U.S. Army ARDEC			ARC	CB-MR-97009	
9. SPONSORING/MONITORING AGE	NCY NAME(S) AND ADDRESS	S(ES)		SORING / MONITORING CY REPORT NUMBER	
U.S. Army ARDEC Close Combat Armaments Center Picatinny Arsenal, NJ 07806-5000			AGEN	CY REPORT NUMBER	
11. SUPPLEMENTARY NOTES					
12a DISTRIBUTION (AVAILABILITY S	STATEMENT		12b. DIST	RIBUTION CODE	
Approved for public release; distribution	on unlimited.				
13. ABSTRACT (Maximum 200 word					
Combustion gases containing hydrogen Although the hydrogen is evolved at ambient temperature.	en can cause severe environmenthe elevated temperatures of con	ntal degradation and cracking mbustion, the deleterious effe	in the high st ects of hydrogo	rength steels used in gun tubes. en on steel are most severe near	
				÷	
14. SUBJECT TERMS				15. NUMEER OF PAGES	
Environmentally-Assisted Cracking, Hydrogen-Induced Cracking, Hydrogen Embrittlement, Propellants, Combustion Gases, High Strength Steels				5 16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT	18. SECURITY CLASSIFICATION OF THIS PAGE	ON 19. SECURITY CLASS OF ABSTRACT	SIFICATION	20. LIMITATION OF AESTRACT	
UNCLASSIFIED	UNCLASSIFIED	UNCLASSIFIED		UL.	

# TABLE OF CONTENTS

	Pag	<u>;e</u>
ACKN	OWLEDGEMENTS	ï
BACK	GROUND	1
DISCU	SSION	1
SUMM	IARY/CONCLUSIONS	2
REFER	RENCES	3
	LIST OF ILLUSTRATIONS	
1.	Schematic of hydrogen embrittlement crack growth rate tests conducted by Williams and Nelson	2

# **ACKNOWLEDGEMENTS**

The authors would like to thank Dr. David Duquette his correspondence on the subject of hydrogen-induced cracking.

#### **BACKGROUND**

Combustion gases containing hydrogen can cause severe environmental degradation and cracking in the high strength steels used in gun tubes. Although the hydrogen is evolved at the elevated temperatures of combustion, the deleterious effects of hydrogen on steel are most severe near ambient temperature. As a general rule, hydrogen-induced cracking failures and stress corrosion cracking failures are easily distinguishable from each other; the former is most severe at ambient temperature, while the latter typically increases in severity with increasing temperature (ref 1). It is, therefore, a conservative and sound engineering approach to test armament materials exposed to hydrogen under ambient temperature conditions.

Hydrogen-induced cracking is a persistent problem. Although much work has been conducted in this area in the past three decades, there are still failures in armament attributed to hydrogen (refs 2-5). Furthermore, hydrogen-related failures can be expected to increase as propellant environments become more severe and as component strength levels increase.

#### DISCUSSION

It is well known that hydrogen-induced cracking presents the greatest problem near room temperature. The classic crack growth rate curves produced by Williams and Nelson (ref 6) on 4130 steel in the presence of a gaseous hydrogen environment show that the fastest crack growth rates are produced at room temperature. A schematic of their results is shown in Figure 1. It is easy to fathom that crack growth rates below room temperature will be lower because of the limited diffusion of the hydrogen into the material. However, the reason for lower crack growth rates above room temperature may not be as obvious. As temperature increases, the diffusivity increases exponentially and greatly increases the likelihood of desorption of the hydrogen. This is the theory behind "baking-out" steels. The phenomenon of maximum hydrogen crack growth rates at room temperature occurs not only with 4130 steel but also with various steels, stainless steels, nickel, titanium, and aluminum alloys.

It seems appropriate, using this information, to test the room temperature behavior of hydrogen-induced cracking of gun tube materials in order to determine the effects of propellant environments. Of course, the ideal test would be the actual firing environment from full-scale tests or from a test chamber; however, these tests are technically challenging, extremely labor intensive, and expensive to conduct. How the hydrogen is produced is irrelevant as long as there are no significant chemical reactions taking place that will bias the test and as long as the amount of hydrogen available is representative of the actual propellant environment. For example, an acid environment can be used to produce hydrogen. However, if the pH of the acid changes over the test duration, so does the amount of hydrogen available to cause cracking. As another option, an electrochemical cell can be used to create hydrogen at the cathode (test material) surface. However, the experimentalist must decide if a "poison" should be used to limit the amount of hydrogen gas formed and must determine the rate at which hydrogen is evolved (varying the current density).




Figure 1. Schematic of hydrogen embrittlement crack growth rate tests conducted by Williams and Nelson.

#### SUMMARY/CONCLUSIONS

- Maximum hydrogen-induced crack growth rates occur at or near room temperature for a wide range of materials, including gun steels.
- Although the hydrogen may be produced from propellants at high temperatures, it is the hydrogen effects at room temperature that are of greatest concern and that cause cracking.
- Testing armament materials in hydrogen-containing environments at room temperature provides a proper measure of the susceptibility of these materials.

#### REFERENCES

- 1. Jones, D. A., *Principles and Prevention of Corrosion*, Prentice-Hall, Inc., NJ, 1996, pp. 235-290.
- 2. Thornton, P. A., et al., "LP Gun No. 2 Materials/Failure Analysis," Internal Report, Benet Laboratories, Watervliet, NY, 1992.
- 3. Thornton, P. A., and Vigilante, G. N., "Analysis of Crack in LP Gun Combustor Liner (ATD #1)," Internal Report, Benet Laboratories, Watervliet, NY, 1993.
- 4. Underwood, J. H., Olmstead, V. J., Askew, J. C., Kapusta, A. A., and Young, G. A., "Environmentally-Controlled Fracture of an Overstrained A723 Steel Thick-Wall Cylinder," *ASTM STP 1189*, American Society for Testing and Materials, Philadelphia, 1993, pp. 443-460.
- 5. Dalley, A. M., Buckman, R. W., Jr., and Bagnall, C., "Physical and Chemical Interactions at the Bore Surface of a Ta-10W Gun Barrel Liner," MPIF-APMI International Conference on Tungsten and Refractory Metals, Washington, DC, 15-16 November 1995.
- 6. Williams D. P., and Nelson, H. G., "Embrittlement of 4130 Steel by Low-Pressure Gaseous Hydrogen," *Metallurgical Transactions*, Vol. 1, January 1970, pp. 63-68.

#### TECHNICAL REPORT INTERNAL DISTRIBUTION LIST

	NO. OF COPIES
CHIEF, DEVELOPMENT ENGINEERING DIVISION ATTN: AMSTA-AR-CCB-DA -DB	1
-DC -DD -DE	1 1 1
CHIEF, ENGINEERING DIVISION ATTN: AMSTA-AR-CCB-E -EA -EB -EC	1 1 1 1
CHIEF, TECHNOLOGY DIVISION ATTN: AMSTA-AR-CCB-T -TA -TB -TC	2 1 1 1
TECHNICAL LIBRARY ATTN: AMSTA-AR-CCB-O	5
TECHNICAL PUBLICATIONS & EDITING SECTION ATTN: AMSTA-AR-CCB-O	3
OPERATIONS DIRECTORATE ATTN: SIOWV-ODP-P	1
DIRECTOR, PROCUREMENT & CONTRACTING DIRECTORATE ATTN: SIOWV-PP	1
DIRECTOR, PRODUCT ASSURANCE & TEST DIRECTORATE ATTN: SIOWV-QA	1

NOTE: PLEASE NOTIFY DIRECTOR, BENÉT LABORATORIES, ATTN: AMSTA-AR-CCB-O OF ADDRESS CHANGES.

#### TECHNICAL REPORT EXTERNAL DISTRIBUTION LIST

	NO. OF COPIES	NO. COPI	
ASST SEC OF THE ARMY RESEARCH AND DEVELOPMENT ATTN: DEPT FOR SCI AND TECH THE PENTAGON WASHINGTON, D.C. 20310-0103	1	COMMANDER ROCK ISLAND ARSENAL ATTN: SMCRI-SEM ROCK ISLAND, IL 61299-5001	1
DEFENSE TECHNICAL INFO CENTER ATTN: DTIC-OCP (ACQUISITIONS) 8725 JOHN J. KINGMAN ROAD STE 0944	2	COMMANDER U.S. ARMY TANK-AUTMV R&D COMMAND ATTN: AMSTA-DDL (TECH LIBRARY) WARREN, MI 48397-5000	1
FT. BELVOIR, VA 22060-6218  COMMANDER		COMMANDER U.S. MILITARY ACADEMY ATTN: DEPARTMENT OF MECHANICS	1
U.S. ARMY ARDEC		WEST POINT, NY 10966-1792	1
ATTN: AMSTA-AR-AEE, BLDG. 3022	1		
AMSTA-AR-AES, BLDG. 321	1	U.S. ARMY MISSILE COMMAND	•
AMSTA-AR-AET-O, BLDG. 183 AMSTA-AR-FSA, BLDG. 354	1 1	REDSTONE SCIENTIFIC INFO CENTER ATTN: AMSMI-RD-CS-R/DOCUMENTS	2
AMSTA-AR-FSA, BLDG. 534 AMSTA-AR-FSM-E	1	BLDG. 4484	
AMSTA-AR-FSS-D, BLDG, 94	1	REDSTONE ARSENAL, AL 35898-5241	
AMSTA-AR-IMC, BLDG. 59	2	122010112 1110211121, 112 00000 02 11	
PICATINNY ARSENAL, NJ 07806-5000	_	COMMANDER U.S. ARMY FOREIGN SCI & TECH CENTER	
DIRECTOR		ATTN: DRXST-SD	1
U.S. ARMY RESEARCH LABORATORY		220 7TH STREET, N.E.	
ATTN: AMSRL-DD-T, BLDG. 305 ABERDEEN PROVING GROUND, MD	1	CHARLOTTESVILLE, VA 22901	
21005-5066		COMMANDER	
DIRECTOR U.S. ARMY RESEARCH LABORATORY ATTN: AMSRL-WT-PD (DR. B. BURNS) ABERDEEN PROVING GROUND, MD		U.S. ARMY LABCOM, ISA ATTN: SLCIS-IM-TL 2800 POWER MILL ROAD ADELPHI, MD 20783-1145	1
21005-5066			

NOTE: PLEASE NOTIFY COMMANDER, ARMAMENT RESEARCH, DEVELOPMENT, AND ENGINEERING CENTER, BENÉT LABORATORIES, CCAC, U.S. ARMY TANK-AUTOMOTIVE AND ARMAMENTS COMMAND, AMSTA-AR-CCB-O, WATERVLIET, NY 12189-4050 OF ADDRESS CHANGES.

# TECHNICAL REPORT EXTERNAL DISTRIBUTION LIST (CONT'D)

NO. COPI			NO. OF COPIES
COMMANDER U.S. ARMY RESEARCH OFFICE ATTN: CHIEF, IPO P.O. BOX 12211 RESEARCH TRIANGLE PARK, NC 27709-221	1	WRIGHT LABORATORY ARMAMENT DIRECTORATE ATTN: WL/MNM EGLIN AFB, FL 32542-6810	1
DIRECTOR U.S. NAVAL RESEARCH LABORATORY ATTN: MATERIALS SCI & TECH DIV WASHINGTON D.C. 20375	1	WRIGHT LABORATORY ARMAMENT DIRECTORATE ATTN: WL/MNMF EGLIN AFB, FL 32542-6810	1

NOTE: PLEASE NOTIFY COMMANDER, ARMAMENT RESEARCH, DEVELOPMENT, AND ENGINEERING CENTER, BENÉT LABORATORIES, CCAC, U.S. ARMY TANK-AUTOMOTIVE AND ARMAMENTS COMMAND, AMSTA-AR-CCB-O, WATERVLIET, NY 12189-4050 OF ADDRESS CHANGES.